

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Solberg et al.

Patent No.: 6,966,264 B2

Issued: November 22, 2005

For: ROCKET MOTORS WITH
INSENSITIVE MUNITIONS SYSTEMS
AND PROJECTILES INCLUDING SAME

Attorney Docket No.: 2507-5836.1US

VIA ELECTRONIC FILING

January 22, 2009

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
OFFICE MISTAKES (37 C.F.R. § 1.322)

Attn.: Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

It is noted that several errors appear in this patent of a typographical nature. These errors are due to mistakes in printing on the part of the U.S. Patent and Trademark Office, and occurred through no fault of the Applicants. A certificate of correction in the form attached hereto is requested.

Please send the Certificate to:

Name: Katherine A. Hamer
Address: TraskBritt
P.O. Box 2550
Salt Lake City, Utah 84110

Attached hereto is Form PTO/SB/44, which is suitable for printing.

Respectfully submitted,



Katherine A. Hamer
Registration No. 47,628
Attorney for Applicants
TRASKBRITT, PC
P.O. Box 2550
Salt Lake City, Utah 84110-2550
Telephone: 801-532-1922

Date: January 22, 2009
KAH/df/slm

Attachment: PTO/SB/44

Document in ProLaw

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,966,264 B2
APPLICATION NO. : 10/645,706
ISSUE DATE : November 22, 2005
INVENTOR(S) : Mark A. Solberg and Robert E. Black

Page 1 of 1

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page:

In ITEM (56) References Cited change "10/1967 Pagel" to --10/1967 Paget--

In the specification:

COLUMN 4, LINE 33, change "rocket motor bum." to --rocket motor burn.--
COLUMN 4, LINE 56, change "a gun gun-launched" to --a gun-launched--
COLUMN 5, LINE 41, change "thereof" to --thereof.--
COLUMN 11, LINES 27-33, delete "An insensitive munitions charge 150 is illustrated positioned in an annular recess of and contacting the tapered rubber insulator 90, with an aft surface of the insensitive munitions charge 150 positioned flush against the forward surface 70 of the flange 60. Although shown having an annular shape, the insensitive munitions charge 150 may have other shapes and"

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Katherine A. Hamer
TRASKBRITT
230 South 500 East, Suite 300
Salt Lake City, Utah 84102 USA

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS.
SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.